

कार्यालय सहायक अभियन्ता-प्रथम प्रान्तीय खण्ड,लोक निर्माण विभाग,शामली

217/1A0

दिनांक 16/2023

प्रबन्धक/प्रधानाचार्य

सैन्ट0आर0सी0,साईटिफिक कांवेन्ट स्कूल पानीपत रोड,कैराना जनपद शामली

विषयः- पानीपत रोड्नेकााना जनपद शामती में सैन्टाआरएसीए,ताईटिशिक कांकेन्ट स्कून की नेशनल बिलिंग कोड 2005 के अनुसार गुणवता एवं शीतिक सत्यापन के सम्बन्ध में। सन्दर्शः- उपखण्ड कार्यातय का पत्रांक 209/1सीए दिनांक 06.06.2023 एवं आएका पत्रांक शून्य दिनांक

उपरोक्त विषयक आपके सन्दर्भित पत्र के क्षम में आपको इस कार्यालय के सन्दर्भित पत्र द्वार क्कूल का मक्चा एवं ANNEX. सम्बन्धित पत्र भरकर पेषित करते हेतु निर्देशित किया गया था,जिसके क्षम में आपके द्वारा दिनके 16,06.2023 को उपस्त्राद कराये गये प्रपत्नों के आधार पर अधीवस्ताकरी द्वारा उस्त्र क्लूल का मिरोक्षण क्थिया गया, जिसके नेशकत विकित्त गरें 3020 के अनुसार Bulliding Safety Conflicate कर्सन्त किया गया है। सामान्य परिस्थितियों में अयन सुरक्षित प्रतीत होता है। सुरक्षा मानकों का मेंद्र अनुपातन,अयन का विकासीकरण,बदलाव कार्य आदि अस्तान निर्मालों की अवहंदना होगी तथा वैदाता स्वयं समाप्त होगी। सुरक्षा मानकों का अनुपालन,भवन का नियमित अनुरक्षण अनिवार्य है। नोटा- प्रमाण पत्र की वैदाता 3 वर्ष है।

सलंग्नकः- Building Safety Certificate

सहायका अभियन्ता-प्रथम प्रान्तीय खण्ड,लो0नि0वि0 शामली

APPNENDIX-XI

BUILDING SAFETY CERTIFICATE

Certified that the existing building St. R.C. Scientific Convent School at Panipat Road, Kairana Distt. Shamli comprised of double storey building owned/occupied by R.C. Scientific Convent School have complied with the building safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of Provincial Division, Public Works Department, Shamli (Uttar Pradesh) on Dated 16.06.2023 in the presence of manager Sh. Arvind Goyal, Mandi , Gandhi Ganj Shamli and that the building/premises is fit for occupancy upto classes XII with effect from 16.06.2023 for a period of three years in accordance with rule and subject to compliance of the specific conditions as appended. Prima facie the construction of building seems to be as per norms of National Building Code rules but in case the building is not found in conformity of detailed National Building Code rules the Public Works Department shall not be held accountable.

Issued on 16.06.2023 at 02:00 PM by Deependra Jaiswal Assistant Engineer, Provincial Division , Public Works Department, Shamli.